

Linac Klystron Status

Linac #1

Linac #2

Linac #3

Linac #4

Linac #5

Linac #6

Linac #7

#005 51.000 hrs

#004 49,000 hrs #006 34,000 hrs #009 42,000 hrs #007 52,000 hrs #010 48,000 hrs #015 34,000 hrs

Linac Holding Stand Linac Holding Stand

#014 500 hrs #001 25,000 hrs **Linac Spare Socket**

#003 800 hrs **Linac Holding Stand**

#011 12,000 hrs

Not pulsed in 4 years

Linac Test Stand

#002 200 hrs Litton

#008 3,000 hrs Litton

#013 0 hrs **Shipping Crate**

#012 0 hrs

Received rebuilt February '99
Tested OK at FNAL

Test Stand Failure due May 99??

Vacuum Failure due August 99??

Vacuum Failure awaiting shipment

Note: Klystron #2 is first to have completed repair/test/return cycle



Linac Klystron Status

Linac #1

#005 53.000 hrs Linac #2

#004 51.000 hrs Linac #3

#006 36,000 hrs Linac #4

#009 44,000 hrs Linac #5

#007 54,000 hrs Linac #6

#010 50,000 hrs Linac #7

#015 36,000 hrs

Linac Holding Stand Linac Holding Stand

#014 500 hrs

#001 25,000 hrs **Linac Spare Socket? Linac Holding Stand**

#003 800 hrs

#011 12,000 hrs

Not pulsed in 4 years

Linac Test Stand?

#002 200 hrs Litton

#008 3,000 hrs In Transit

#013 0 hrs

Litton

#012 0 hrs

Test Stand Failure Vacuum Failure Received rebuilt February '99 Rebuilt July '99 Tested OK at FNAL awaiting repair due May 99?? awaiting test at FNAL

Note: Klystrons #2 and #13 have completed repair/test/return cycle



Linac Klystron Status

Linac #1

#005 55,000 hrs Linac #2

#004 53,000 hrs Linac #3

#006 37,000 hrs Linac #4

#009 46,000 hrs Linac #5

#007 55,000 hrs Linac #6

#010 51,000 hrs Linac #7

#015 38,000 hrs

Linac Holding Stand

#014 500 hrs Lab G

#001 25,000 hrs **Linac Holding Stand**

#003 800 hrs **Linac Test Stand**

#011 12,000 hrs

Linac Holding Stand

#002 200 hrs

Received rebuilt February '99
Tested OK at FNAL

Litton

#008 3,000 hrs

Test Stand Failure awaiting repair

Litton

#013 0 hrs

Rebuilt July '99 returned w/water leaks

Litton

#012 0 hrs

Vacuum Failure awaiting repair

Note: Klystrons #2 and #13 have completed repair/test/return cycle, though #13 was found to have water leaks and returned.



Linac Klystron Status

Linac #1

#005 57,000 hrs Linac #2

#004 56,000 hrs Linac #3

#006 40,000 hrs Linac #4

#009 48,000 hrs Linac #5

#007 58,000 hrs Linac #6

#010 54,000 hrs Linac #7

#015 40,000 hrs

Linac Holding Stand

#014 500 hrs Lab G

#001 25,000 hrs

Vacuum Failure awaiting shipment **Linac Holding Stand** Linac Holding Stand

#003 800 hrs

#011 12,000 hrs

Linac Holding Stand

#002 200 hrs

Received rebuilt February '99 Tested OK at FNAL

Litton

#008 3,000 hrs

Test Stand Failure awaiting repair

Linac Test Stand

#013 0 hrs

Received rebuilt Dec '99 awaiting test at FNAL

Litton

#012 0 hrs

Vacuum Failure awaiting repair

Note: Klystrons #2 and #13 have completed repair/test/return cycle, #13 is being prepared for test stand check-out.



Linac Klystron Status

Linac #1

#002

2,000 hrs

Linac #2

#004 62,000 hrs Linac #3

#006 46,000 hrs Linac #4

#009 54,000 hrs Linac #5

#007 64,000 hrs Linac #6

#013 2,300 hrs Linac #7

#015 46,000 hrs

Linac Test Stand

#014 500 hrs Lab G

#011 13,500 hrs **Linac Holding Stand**

#003 800 hrs **Linac Holding Stand**

#010 57,400 hrs

Removed from K6 8/00 w/ filament circuit problems

To be shipped to Litton

#005 63,000 hrs

Failed in K1 10/00

Litton

#008 3,000 hrs

Test Stand Failure

11/00 promise date

Litton

#001 25,00 hrs

Lab G vacuum problems 2/01 promise date

Litton

#012 0 hrs

Vacuum Failure 12/00 promise date

Note: Klystrons #2 and #13 have completed repair/test/return cycle.